



Buckeye Rd

Replaced broken
no camping sign

Installed new
vault toilet

Delineated Parking area

Interpretive panels
(2) at site of
decommissioned use
trail. HTNF has spare
copies of panels

Picnic tables
and pad
installed

Established trail

Restoration site sign
installed to keep
people on main trail,
horizontal mulch added

Restoration site
sign installed to
keep people on main
trail and prevent
resource damage

Crucial
location
for sign

Buckeye Creek

Buckeye Creek

Adjacent to Hotsprings -
restoration of meadow. 5
fire pits decommissioned